


Rúry



de	e	hrdlované		nehrdlované
		L1	Ls	Ls
32	1,8	34	-	4000
40	1,8	36	-	4000
50	1,8	38	300,500,1000,2000,4000	4000
63	1,8	41	-	4000
75	1,8	43	500,1000,2000,4000	4000
110	2,2	54	500,1000,2000,3000,4000	4000
125	2,5	61	500,1000,2000,3000,4000	4000
140	2,8	54	500,1000,2000,3000,4000	4000
160	3,2	74	500,1000,2000,3000,4000	4000