


Tvarovka FNP PN 10



dn	DN	L	d1	d2	d3	z
90	80	142	108	80	125	38
110	100	153	131	100	150	39
160	150	176	188	150	213	45
225	200	218	248	200	273	56
315	300	252	352	285	376	60